

# Fault Report

Customer Name: Brown	Date: 22/02/24
Customer Reference: 6749	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Pf roller rh door	
Fault Description:  Blind has been made smaller than asked for. Material also seem to small in width as can see down the side in the frame	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  New blind needed at 539 width  50 20mm and 50 22mm pf brackets needed as well And 12 sets of lh and rh pf bottom bar end caps/stoppers	