

# Fault Report

Customer Name: Newmans	Date: 06/02/24
Customer Reference: 7258	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Slats only	
Fault Description:  Slats been made wrong size, allowance for track not taken off.	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  Slats remade at recess size.	