

UK 6260
TAYLOR/R

Fault Report

FITTER NAME: David	FITTING DATE: 15/08/24
Customer Name: Taylor	
Customer Ref: 6260	
Salesperson: Mike	Salesperson called: No
Blind Type and number: Lounge 2 shutter	
Problem fixed on site: No	
Fault Description One of the slats on the right hand door on the second lounge shutter has a crack in it Pictures sent in.	
Action to Correct:- New slat needed	