


ON LTTU/R

at the ...

Fault Report

FITTER NAME: David		FITTING DATE: 12/11/2024	
Customer Name: Mcallister			
Customer Ref: 7518			
Salesperson: Ronnie		Salesperson called: Yes/No	
Blind Type and number: All rollers			
Problem fixed on site: Yes/No			
Fault Description			
Blinds have been made with the wrong shaped scallop at the bottom.			
Action to Correct:-			
 IS WHAT THEY SHOULD BE.			
LIVBAT MIDDLE ALSO NEEDS 10MM TAKEN OFF WIDTH			