

Fault Report

FITTER NAME: David		FITTING DATE: /2024	
Customer Name: Collum			
Customer Ref: 7330			
Salesperson: Ronnie		Salesperson called: Yes/No	
Blind Type and number: Office shutter			
Problem fixed on site: Yes/No			
Fault Description Wrong type of frame for the bottom part			
Action to Correct: New sill frame for the bottom Shutter has been fitted without the bottom frame so they have something up.			