

Fault Report

SB 7920
Darby / K

Customer Name: DARBY	Date: 15-7-25
Customer Reference: 7920	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: ROLLER CHAIN CURTAIN	
Fault Description: CHAIN KEEPS COMING UNDOWE WHEN CUSTOMER PULLS IT CUSTOMER CAN'T PULL CURTAINS CLOSED DUE TO LENGTH OF IT	
Action to correct: NEW CHROME CONTINUOUS CHAIN AT 3050 FITTING HEIGHT POLES TO PULL CURTAINS NEEDS.	