

Fault Report

Customer Name: MASON	Date: 1-4-26
Customer Reference: 8253	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No ↓
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: INTU VENETIAN	
Fault Description: TOP SLAT NOT STICKING	
Action to correct: New TOP RAIL END CAPS NEEDED 2 LEFT HAND 2 RIGHT HAND 4 etc	

