

Fault Report

Customer Name: Llunaworth	Date: 29/4/22
Customer Reference: 20397	Fitter: Michael
Salesperson: Walter	Salesperson called: Yes (No)
Blind Type and number: Roman	
Fault Description: measured too short in drop	
Action to correct: new blind ordered	
Problem fixed on site: Yes (No)	
Further action required: yes	