

20527
Patterson.R

Fault Report

Customer Name: Patterson	Date:
Customer Reference: 20527	Fitter: ROSS
Salesperson: MARDIN	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: VERT	
Fault Description: WILL SEND BACK IN VAN	
Action to correct: 2 headrails for alteration make right hand split on BOTH	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: yes	