

GRAMPAN - 21146 - MCKENZIE

2 PERFECT FIT SHAPES MISMEASURED

1 FREEHANGING ELECTRIC NEEDS CUT DOWN
THERE WERE 3 IN A ROW - TOO TIGHT

POSSIBLE PROBLEM WITH FABRIC LOOKS
TWISTED, WE WILL SEE IF SETTLES. I TOOK
WEIGHT OUT OF IT. I HAVE NEW SIZES

