

Fault Report

Customer Name: 0126	Date: 13/4/23
Customer Reference: STEWART	Fitter: RB
Salesperson: MC	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Senses .	
Fault Description: Factory did not put end caps on do headbox for ditter	
Action to correct: Fitter did it & marked the fabric Please can end caps be put on .	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes	