

# Fault Report

Customer Name: 22424	Date:
Customer Reference: Rejo	Fitter: RB
Salesperson: MP	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Vert headrail	
Fault Description: Customer says rail too short, could see card from outside now wants wand.	
Action to correct: 2150 x 1395 recess wand control left-wand. Right Bunch	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	