

Fault Report

Customer Name: PHIMSTER	Date: 23/11
Customer Reference: 23389	Fitter:
Salesperson: SCOT	Salesperson called: Yes/No
Blind Type: INTU VEN	
Fault Description: SIZES WRONG WAY ROUND	
Action to correct: NEW INTU	
Problem fixed on site: Yes/No NO	
Further action required: YES	