

Fault Report

FITTER NAME: MICHAEL	FITTING DATE: 11/10/24
Customer Name: Morrison	
Customer Ref: 4147. SR	
Salesperson: SCOTT	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Vert 1 - 5	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Fault Description All rails are meant to be brown to match the windows. Living room slats too long should be 1558 recess	
Action to Correct:- Remake all rails in brown. remake living slats @ 1558 recess.	