

# Fault Report

FITTER NAME: MICHAEL	FITTING DATE: 21-08-24
Customer Name: SHAHEEN	
Customer Ref: 24679	
Salesperson: SCOT	Salesperson called: Yes/No <u>    </u>
Blind Type and number: VERTICALS	
Problem fixed on site: Yes/No <u>    </u>	
Fault Description MISMEASURE - SLATS SHOULD BE 1118MM RECESS INSTEAD OF 1180MM.	
Action to Correct:- REMAKE SLATS	