

4159

LINDSAY / R

GB28888R.

Fault Report

FITTER NAME: MICHAEL	FITTING DATE: 01/10/24
Customer Name: LINDSAY	
Customer Ref: 4159	
Salesperson: SCOT	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: Ven 2	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Fault Description Cord had snapped tried to fix onsite but cord wasn't long enough so doesn't tilt properly now. Also had to remove clear clips as 2 intus were missing them on another job.	
Action to Correct:- Record blind and needs new clear clips on the top	