

Fault Report

Customer Name Mr Broderick	Date; 5/11/24
Customer Reference: 24961	Fitter Michael
Salesperson:	Salesperson called: Yes
Fault Description: Blinds are 6½ inches away from window.	
Action to correct: Nothing can be done recess is too small to top fix. its on STD FF brackets	
Problem fixed on site: <input checked="" type="radio"/> Yes / <input type="radio"/> No	
Further action required: NO	