

Fault Report

Customer Name BUCHAN	Date; 30/10/24
Customer Reference: 25077	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Slats in Living too long. Tried to flip hanger but don't fit onto rail	
Action to correct: Remake slats at 1290 Recess	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	