

Fault Report

Customer Name Latto	Date; 14/12/24
Customer Reference: 25113	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Master rail came as RR. instead of LL	
Action to correct: Remake as LL	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:	