

# Fault Report

Customer Name CUMMINGS	Date; 22/01/25
Customer Reference: 25271	Fitter MICHAEL
Salesperson: DAVID	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 1 x Roller too big needs cut down to 1190 recess and reverse rolled	
Action to correct: Cut down to 1190 recess & reverse roll	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes	