

Fault Report

| | |
|---|------------------------------------|
| Customer Name PARK | Date; 25/11/24 |
| Customer Reference: 23863 | Fitter MICHAEL |
| Salesperson: SCOT | Salesperson called: Yes/ No |
| Fault Description: Blend too small apparently he measured it from the outside for some reason | |
| Action to correct: remake at 1460mm Access | |
| Problem fixed on site: Yes/ No | |
| Further action required: Yes | |