

Fault Report

Customer Name Khan	Date: 19/12/24
Customer Reference: 25069	Fitter Mok
Salesperson: Stuart	Salesperson called: Yes/No <input checked="" type="radio"/> No
Fault Description: Tie back hooks missing	
Action to correct: order chrome tie back hooks.	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required: post hooks to customer	