

29/1

# Fault Report

|   |                            |
|---|----------------------------|
| Customer Name<br>Wkechuku   | Date;<br>13/1/25           |
| Customer Reference:<br>25038  | Fitter                     |
| Salesperson:  | Salesperson called: Yes/No |
| Fault Description:<br>In to venetian requires to be<br>restung & retensioned. |                            |
| Action to correct:<br>FAR TOO TIGHT!  |                            |
| Problem fixed on site: Yes/No   |                            |
| Further action required:  |                            |