

Fault Report

Customer Name NELSON	Date; 30/01/25
Customer Reference: 4177	Fitter MICHAEL
Salesperson: STUART	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Fault Description: Blind 2 in utility should be STD ven not p/fit	
Action to correct: Remake as STD ven.	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: Yes	