

Fault Report

Customer Name MILNE	Date; 27/02/25
Customer Reference: 25516	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes <input checked="" type="radio"/> No
Fault Description: Rail should only have 31 Runners but has 32	
Action to correct: Remake rail with 31 Runners	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Yes remake rail with 31 Runners instead of 32	