

# Fault Report

|   |  |
|---|--|
| Customer Name<br>KINGHORN   | Date;<br>28/02/25  |
| Customer Reference:<br>0507   | Fitter<br>MICHAEL  |
| Salesperson:<br>STUART  | Salesperson called: Yes/ <input checked="" type="radio"/> No |
| Fault Description:<br>BLIND NO 1 SHOULD BE 1771 x 1128<br>RECESS NOT 1171 |  |
| Action to correct:<br>REMAKE AS 1771 mm Recess                            |  |
| Problem fixed on site: Yes/ <input checked="" type="radio"/> No           |  |
| Further action required:<br>YES, REMAKE BLIND AND RETURN<br>TO FIT        |  |