

Fault Report

Customer Name KINGHORN	Date; 28/02/25
Customer Reference: 0507	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: BLIND NO 1 SHOULD BE 1771 x 1128 RECESS NOT 1171	
Action to correct: REMAKE AS 1771 mm Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: YES, REMAKE BLIND AND RETURN TO FIT	