

# Fault Report

Customer Name MIDDLETON	Date; 09/04/25
Customer Reference: 25605	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No

Fault Description:

BLIND NO 2 SLATS TO LONG  
SHOULD BE 1117mm RECESS

Action to correct:

REMAKE SLAT AT 1117MM RECESS

Problem fixed on site: Yes/No

Further action required:

YES, REMAKE SLATS AND RETURN TO  
FIT