

Fault Report

Customer Name MACASKIL	Date; 11/03/25
Customer Reference: 25450	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes <input checked="" type="checkbox"/> No
Fault Description: Customer wanted the rollers reverse rolled, I tried to do this onsite but couldn't get it to work think the spring broke	
Action to correct: NEW SPRING AND REVERSE ROLL KEEP ON LH AS BRACKETS ARE UP	
Problem fixed on site: Yes <input checked="" type="checkbox"/> No	
Further action required: YES 2 32mm Nbe Springs ordered.	