

Fault Report

Customer Name IPS Group	Date; 13/6/25
Customer Reference: GBCO44	Fitter Ama
Salesperson: Lewis	Salesperson called: Yes/No
Fault Description: Rafter blind not too small	
Action to correct: Blind to be remade at 1952 recess	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Blind to be remade and go back to Gt.	