

# Fault Report

Customer Name Gladys Nicol	Date; 14/04/25
Customer Reference: 25561	Fitter Michael
Salesperson: Lewis	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Headrail roller stuck - see pic	
Action to correct: replace headrail	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: new headrail to be made FOC and installed for customer.	



