

Fault Report

Customer Name Little	Date; 17/4/25
Customer Reference: ZSS11	Fitter Michael
Salesperson: Stuart	Salesperson called: Yes/No
Fault Description: Scratch on bottom bar and threads on blind of blind 2 (1420)	
Action to correct: re-make Blind 2 (1420)	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: re-make & return to refit blind	

changed mind called to say only re-make bottom bar and refit.