

Fault Report

Customer Name BISSETT	Date; 29/06/25
Customer Reference: 25813	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Roller too big ^{should be} 1460 Recess	
Action to correct: Cut down to 1460 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes, cut down return to fit.	