

# Fault Report

Customer Name McGregor	Date; 09/05/25
Customer Reference: <del>LEWIS</del> 25694	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description:  Slats too long. should be 2305 recess.	
Action to correct:  Remake slats @ 2305 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:  YES, Remake slats.	