

# Fault Report

Customer Name DRUMMOND	Date; 30/06/25
Customer Reference: 25834	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: <input checked="" type="checkbox"/> Yes/No
Fault Description: Roller too big should be 1726 Recess Vertical NOS should be RH Control LH stack	
Action to correct: Cut down roller, remake vert rail	
Problem fixed on site: Yes/ <input checked="" type="checkbox"/> No	
Further action required: Yes, cut down/Remake & return to fit.	