

Fault Report

Customer Name OYIBOCHA	Date; 13/05/25
Customer Reference: 25597	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Miss measure on P/fit should be 1759mm	
Action to correct: Remake @ 1759mm	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: YES, Remake & Return to fit.	