

# Fault Report

Customer Name DONELLY	Date; 19/05/25
Customer Reference: 25754	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Fault Description: Roller too big should be 1169 Recess, Recess smaller at top than bottom	
Action to correct: cut blind down to 1169 Recess	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: Yes, cut down and return to f.t.	