

Fault Report

Customer Name MCGINTY	Date: 10/07/25
Customer Reference: 25916	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called <input checked="" type="radio"/> Yes <input type="radio"/> No
Fault Description: Customer wanted kids bed in the recess but measured for face	
Action to correct: NEEDS CUT DOWN TO 1030mm RECESS	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: Cut down & Return to fit.	

8
miles
15
min
10
min
7
min
1
by