

# Fault Report

Customer Name ROBERTSON	Date; 23/07/25
Customer Reference: 25961	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 2 x missmeasures blinds Wood no 3 should be 1450 recess Roller no 2 should be 1289 recess.	
Action to correct: Remake / cut down as above.	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes remake / cut down an return to fit.	