

THUS 24/7 9-12.

Fault Report

Customer Name Crook	Date; 29/06/25
Customer Reference: 0541	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="checkbox"/> No
Fault Description: Rollers should be brown brackets & components (mechanisms) verts in conserv should have brown extension brackets (slats hitting brkts)	
Action to correct: supply new components & brackets.	
Problem fixed on site: Yes/ <input checked="" type="checkbox"/> No	
Further action required: yes, supply new brackets & ref.it.	