

Fault Report

Customer Name Anderson	Date; 05/08/25
Customer Reference: 0576	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Blind NO1 manufactured @ 1354 instead of 1454 Blind no 3 too wide should be 970mm recess	
Action to correct: Remake blinds 1 & 3	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes remake & return to fit.	