

Fault Report

Customer Name BEATTIE	Date; 22/08/25
Customer Reference: 26142	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Missmeasure blind NO 9 should be 638 x 1817 beadfit. ↑ End Cap missing	
Action to correct: Reorder blind & LHS top end cap	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes, reorder & return to fit.	