

Fault Report

Customer Name <i>Technip</i>	Date; <i>02/09/25.</i>
Customer Reference: <i>9BC073</i>	Fitter <i>Jay Michael</i>
Salesperson: <i>Jay</i>	Salesperson called: Yes/No
Fault Description: <i>Slots should be 1545 recess</i>	
Action to correct: <i>rework slots.</i>	
Problem fixed on site: Yes/ <u>No</u>	
Further action required:	