

Fault Report

Customer Name Ricketts	Date; 15/09/25
Customer Reference: 26151	Fitter Michael
Salesperson: Lewis	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Fault Description: Slats are 10mm too short	
Action to correct: order slats 10mm longer for Master only	
Problem fixed on site: <input checked="" type="radio"/> Yes/ <input type="radio"/> No	
Further action required: 	