

Fault Report

Customer Name Barbour	Date:
Customer Reference: 26208	Fitter Micheal
Salesperson: Lewis	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Fault Description: Wrong control side was orderd and Fitted on Blind ①	
Action to correct: Order Blind ① with Left control	
Problem fixed on site: <input checked="" type="radio"/> Yes / <input type="radio"/> No	
Further action required: Re-order + Fit Blind ① with correct Left control side	