


Fault Report

Customer Name BUCHAN	Date: 10/11/25
Customer Reference: 26404	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Curved track to small	
Action to correct: Remake track	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Remake track & return to fit.	

26404 - Buchon

Beck

26404



P/CUST	
NET	
PRESS	
RADIO	
MAG.	
VAN	
RECC.	
SHOP	
TV	
YELL P	
OTHER	

tone fix	brackets top face
	-

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
Lounge	2775 ✓	1925 ✓	25 Ven ✓	0150 ✓	RH ✓	2400 ✓	225 452
↓	3800 ✓	—	track	2x Bends 90°	—	2400	225
↓	3500 ✓	2040 ✓	curtain	Malay Oat © ✓ STP. IVORU Linina			985