

Fault Report

Customer Name Rice	Date: 3-12-25
Customer Reference: 0533	Fitter DAVID
Salesperson: Lewis	Salesperson called: Yes/No
Fault Description: UTILITY + Kitchen SLATS Too Long	
Action to correct: New SLATS needed AT 1117 DROP (Recess) FOR BOTH	
Problem fixed on site: Yes/No	
Further action required: New SLATS AT 1117 DROP FOR BOTH (Recess)	