

Fault Report

Customer Name DEESIDE GOLF	Date: 16/12/25
Customer Reference: GR110	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: 2 x Missmeasures	
Action to correct: Blind NO 2 Cut down to 1385 Recess Blind NO 6 Cut down to 1396 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Cut down & return to f.f.	