

Fault Report

Customer Name BROWN	Date; 02/03/26
Customer Reference: 26906	Fitter MICHAEL
Salesperson: Kevin	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Blind No1 slats too long	
Action to correct: Get Remake. slats @ 1110 mm	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Remake slats & return to fit	