

Fault Report

Customer Name INGRAM	Date: 03/03/26
Customer Reference: 26922	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Mismeasure width & drop	
Action to correct: Remake at 1445 x 1450 recess	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Yes remake & return to fit-	

DATE

8
miles
15
min

-R

15
miles
3
m

74R

E

Customer Privacy Policy
https://www.ingram.com/privacy-policy